



**3D BLINDS**

VERSION — 4 JAN' 24

Fabric	System	Unit
	Chain 38 w/ Valance	
<b>DIMOUT 55MM</b>		
Seri 3D 11	1.915	/m <sup>2</sup>
Seri 3D 10	2.075	/m <sup>2</sup>
<b>ACCESSORIES</b>		
Wall Mount	8	/piece
Bottom	Bulat	-
Component Colour	<input type="checkbox"/>	-

\*harga dalam ribuan rupiah

**Keterangan**

1. Minimum ukuran L & T dihitung 1m
2. Khusus seri 3D 10xx check lebar ukuran di modul batas ukuran

## 3D BLINDS



Fabric	System	Unit
	Chain 38 w/ Pulley & Valance	
<b>DIMOUT 55MM</b>		
Seri 3D 11	2.115	/m <sup>2</sup>
Seri 3D 10	2.275	/m <sup>2</sup>
<b>ACCESSORIES</b>		
Wall Mount	8	/piece
Bottom	Bulat	-
Component Colour	<input type="checkbox"/>	-

\*harga dalam ribuan rupiah

### Keterangan

1. Minimum ukuran L & T dihitung 1m
2. Khusus seri 3D 10xx check lebar ukuran di modul batas ukuran

## 3D BLINDS



Fabric	System				Unit
	Tube 50	Tube 50 w/ Valance	Tube 63	Tube 63 w/ Valance	
<b>DIMOUT 55MM</b>					
Seri 3D 11	1.295	1.340	1.340	1.370	/m <sup>2</sup>
Seri 3D 10	1.450	1.495	1.495	1.525	/m <sup>2</sup>
<b>ACCESSORIES</b>					
Joint System	1.573	-	458	-	/piece

\*harga dalam ribuan rupiah

### Keterangan

1. Minimum ukuran L & T dihitung 1m
2. Khusus seri 3D 10xx check lebar ukuran di modul batas ukuran

Somfy®	System				Unit
	Altus 40 4/16 Receiver	Sonesse 40 6/20 Receiver	Altus 50 6/32 Receiver	Altus 50 10/32 Receiver	
<b>ALUMINIUM</b>					
Tube 50mm	500	500	-	-	/mL
Tube 50mm w/ Valance	1.170	1.170	-	-	/mL
Tube 63mm	-	-	1.170	1.170	/mL
Tube 63mm w/ Valance	-	-	1.850	1.850	/mL
<b>MOTOR</b>					
Tube 50mm	6.470	10.690	-	-	/set
Tube 50mm w/ Valance	6.470	10.690	-	-	/set
Tube 63mm	-	-	8.580	9.350	/set
Tube 63mm w/ Valance	-	-	8.580	9.350	/set
<b>ACCESSORIES</b>					
Wireless Wall Switch 1	1.191	1.191	1.191	1.191	/piece
Situo 1	1.008	1.008	1.008	1.008	/piece
Situo 2	1.492	1.492	1.492	1.492	/piece
Situo 5	1.895	1.895	1.895	1.895	/piece
Telis 16	6.082	6.082	6.082	6.082	/piece
Telis 6 w/ Timer	6.887	6.887	6.887	6.887	/piece
Situo Variation 1	-	2.578	-	-	/piece
Situo Variation 4	-	3.223	-	-	/piece
Sun Sensor	5.512	5.512	5.512	5.512	/piece

\*harga dalam ribuan rupiah

**Keterangan**

1. Minimum ukuran L Aluminium dihitung 1mL

Somfy®	System					Unit
	Ariane 50 6/32 External Receiver	Atlas 50 15/32 External Receiver	Atlas 50 15/17 External Receiver	Sonesse Ultra 50 6/20 Receiver (Quiet)	ILT 50 6/32 External Receiver	
<b>ALUMINIUM</b>						
Tube 50mm	-	-	-	-	-	/mL
Tube 50mm w/ Valance	-	-	-	-	-	/mL
Tube 63mm	1.170	1.170	1.170	1.170	1.170	/mL
Tube 63mm w/ Valance	1.850	1.850	1.850	1.850	1.850	/mL
<b>MOTOR</b>						
Tube 50mm	-	-	-	-	-	/set
Tube 50mm w/ Valance	-	-	-	-	-	/set
Tube 63mm	11.845	12.375	12.460	17.095	13.785	/set
Tube 63mm w/ Valance	11.845	12.375	12.460	17.095	13.785	/set
<b>ACCESSORIES</b>						
Wireless Wall Switch 1	1.191	1.191	1.191	1.191	1.191	/piece
Situo 1	1.008	1.008	1.008	1.008	1.008	/piece
Situo 2	1.492	1.492	1.492	1.492	1.492	/piece
Situo 5	1.895	1.895	1.895	1.895	1.895	/piece
Telis 16	6.082	6.082	6.082	6.082	6.082	/piece
Telis 6 w/ Timer	6.887	6.887	6.887	6.887	6.887	/piece
Situo Variation 1	2.578	2.578	2.578	-	-	/piece
Situo Variation 4	3.223	3.223	3.223	-	-	/piece
Sun Sensor	5.512	5.512	5.512	5.512	5.512	/piece

\*harga dalam ribuan rupiah

**Keterangan**

1. Minimum ukuran L Aluminium dihitung 1mL

Alia®	System				Unit
	AM 35 6/28 Receiver	AM 35 6/28 Receiver (Zero Gap)	AM 45 10/30 Receiver	AM 45 6/28 External Receiver (Quiet)	
<b>ALUMINIUM</b>					
Tube 50mm	500	500	-	-	/mL
Tube 50mm w/ Valance	1.170	-	-	-	/mL
Tube 63mm	-	-	1.170	1.170	/mL
Tube 63mm w/ Valance	-	-	1.850	1.850	/mL
<b>MOTOR</b>					
Tube 50mm	2.220	2.880	-	-	/set
Tube 50mm w/ Valance	2.220	-	-	-	/set
Tube 63mm	-	-	2.525	2.910	/set
Tube 63mm w/ Valance	-	-	2.525	2.910	/set
<b>ACCESSORIES</b>					
Wireless Wall Switch 1	419	419	419	419	/piece
Wireless Wall Switch 2	479	479	479	479	/piece
Remote 1	364	364	364	364	/piece
Remote 2	390	390	390	390	/piece
Remote 6	415	415	415	415	/piece

\*harga dalam ribuan rupiah

**Keterangan**

1. Minimum ukuran L Aluminium dihitung 1mL
2. Khusus motor AM35 6/28 Receiver (Zero Gap) hanya untuk motor posisi kiri & tidak bisa joint sistem